

20230523 Non-function quickshif (clutchmaster) function at DCCDIP v109 (firmware 221221a).

This firmware contains bug. Non-function quickshif (clutchmaster) function at DCCDIP v109 (firmware 221221a).

You can to update firmware [HERE](#) (DCCDIP).

IgniTech

Českobratrská 84

535 01 PŘELOUČ

ignitech@ignitech.cz

www.ignitech.cz